

MODEL: AX60

No. MS-0008

DATE: March 1986

001 Subject: To improve performance

The ROM IC program has been changed to improve the following points.

1. AUTO TUNE request by MIDI is recognized but is not transmitted.
2. AUTO MUTE request by AUTO MUTE button is accepted up to 6 times causing other functions inoperative for up to 30 - 35 seconds.
3. When VERIFY is executed and the data recorded on the tape and that of AX60 is different whatever the reason may be, the data in AX60 may be re-written when PROTECT switch is off.
4. Since the position of PITCH BEND setting VR is memorized when the unit is turned off, when the unit is turned on again after changing the position of setting VR, the amount of Pitch Bend effect is different from its VR position.
5. In SPLIT mode, the MIDI channels are set for Upper keys and Lower Keys separately. But even after SPLIT mode is released, MIDI channels are not canceled thus AX60 accepts 2 MIDI channels.

|       | Ref. No. | Part No.  | Description             |
|-------|----------|-----------|-------------------------|
| (NEW) | 3-IC7    | EI-364674 | IC TMM2764ADC AX60 V1.2 |

Changed from : January 1986

Service Ref. No. : CNL0101, CNL0113

MODEL: AX60

No. MS-0008

DATE: March 1986

002 Subject: Standardization of parts

In order to accommodate the same power supply P.C. Board as of AX73, the circuit has been changed as follows.

|          | Ref. No. | Part No.  | Description     |
|----------|----------|-----------|-----------------|
| (FORMER) | 7-R7     | ER-364324 | R MF H 1/4W 14K |
| (NEW)    | 7-R7Z    | ER-305128 | R MF H 1/4W 15K |
| (FORMER) | 7-VR1Z   | EV-364326 | R S-FIX 2.2K    |
| (NEW)    |          | Deleted   |                 |

Changed from : April 1986

Service Ref. No. : CNA1861